



Turning Power on:

Open default show file. Press green macro buttons. These park channels 4001 (FOH), 4002 (DS of MS Full Black), 4003 (US of MS Full Black).

For Touring Companies who only want a hardline of DMX:  
Run hard line to the fly floor and plug into splitters.

For Touring Companies who want to use a nomad:  
Load their showfile onto our Gio (boot as primary).  
Give them our Nomad (boot as client).

Universe Allocation:

- 1: FOH, Dimmers, House Lights.
- 2: LX 1, 2, 4 (Down Specials)
- 3: LX 3 5 6 (Pars, Batterns, Movers)

Adding New Networked Devices to the Network:  
Plug Device into Ethernet Switch.  
Set Subnet Mask to 255.255.0.0  
Set IP address to 10.101.X.Y (X and Y can be anything between 1 and 254 but cannot be the same address as something already on the network – Check ETC Website for default IP Addresses)